



Care and Cleaning Information for Bulwark® FR Hi-Visibility Rainwear

Bulwark flame resistant high visibility rainwear is constructed from a blend of NOMEX and KEVLAR fibers coated with PVC. These garments have welded seams for waterproof performance and provide limited protection from incidental chemical splash. Where major chemical exposure is a concern, appropriate specialized barrier garments should be selected.

Flame resistant garments should be removed immediately and replaced with clean FR apparel if they become fouled with flammable materials.

Bulwark flame resistant high visibility rainwear meets the requirements of ASTM F1891-2002 for arc and flame resistant rainwear and ISEA/ANSI 107-2004 for high visibility. When worn separately, the jacket is rated ANSI Class 2, Level 2. When worn with the matching bib, the ensemble rates Class 3, Level 2.

These garments can be wiped clean using a damp cloth or home laundered in cold water using the gentle cycle. Hang to dry.

INDUSTRIAL LAUNDRY

- Bulwark FR high visibility rainwear should be home washed only.

HOME WASH

- Hand or machine wash cold (104°F, 40°C) on gentle cycle using mild detergent. Do not use solvents or abrasive cleaners. Hang to dry. Do not use any type of bleach. Do not use fabric softeners. Do not iron.

DRY CLEAN

- Do not dry clean.

REPAIR & MENDING

- These garments may not be repaired. Any Bulwark rainwear that is torn, ripped, or exposed to flames or electric arcs, must be removed from service and replaced.

The information in this bulletin is based on the results of testing in our laboratory and information from the fabric vendor. It is provided for your guidance and knowledge. As of the publication date, this bulletin contains up to date information on care and cleaning. Please visit our website at www.bulwark.com for the latest information.